

# Evidencija o posetama radi održavanja

KONE nalog 000872388612

Broj ugovora 41890846

Naziv lokacije EMPIRET DOO BEOGRAD-NOVI BEOGRAD

SAP broj opreme 44011776

Serijski broj proizvođača 44011776

ID Opreme L2

Adresa TREŠNJINOG CVETA 11

Grad BEOGRAD

Poštanski broj 11090

Prisustvovao Milos DUBAK

Datum posete 3/11/2026 5:44:11 PM

|                                                                                  |                     |
|----------------------------------------------------------------------------------|---------------------|
| Evidencija servisnih usluga                                                      |                     |
| <b>Задаци на доњем прилазу</b>                                                   | <b>Modul status</b> |
| Verification of entrance and corridor                                            | ✓                   |
| Verification of landing signalization                                            | ✓                   |
| Verification of landing door panels and landing door running                     | ✓                   |
| Verification of landing door sill                                                | ✓                   |
| Verification of elevator car door sill                                           | ✓                   |
| <b>Задаци на највишем спрату</b>                                                 | <b>Modul status</b> |
| Verification of car door operator                                                | ✓                   |
| Verification of car door operation                                               | ✓                   |
| Verification of door operator belt                                               | ✓                   |
| Verification of car door contact and lock contact                                | ✓                   |
| Проверите профил шине                                                            | ✓                   |
| Verification of synchronization rope or chain                                    | ✓                   |
| <b>Задаци за кров кабине лифта</b>                                               | <b>Modul status</b> |
| Verification of guide rail lubricator; if applicable                             | ✓                   |
| Check elevator car roof stop switch(es) and inspection drive unit, if applicable | ✓                   |
| <b>Задаци на крову кабине лифта за врата на највишем прилазу</b>                 | <b>Modul status</b> |
| Verification of landing door railing                                             | ✓                   |
| Verification of landing door lock                                                | ✓                   |
| Verification of landing door contact and lock contact                            | ✓                   |
| Verification of closing weight or spring                                         | ✓                   |


|                                                                               |                     |
|-------------------------------------------------------------------------------|---------------------|
| Verification of landing door bottom guides                                    | ✓                   |
| Verification of landing door closed gap                                       | ✓                   |
| <b>Задаци на крову кабине лифта за све међуспратове</b>                       | <b>Modul status</b> |
| Verification of landing door railing                                          | ✓                   |
| Verification of landing door lock                                             | ✓                   |
| Verification of landing door contact and lock contact                         | ✓                   |
| Verification of closing weight or spring                                      | ✓                   |
| Verification of landing door bottom guides                                    | ✓                   |
| Verification of landing door closed gap                                       | ✓                   |
| <b>Задаци у кабини лифта на прилазу</b>                                       | <b>Modul status</b> |
| Verification of door open button and car door running                         | ✓                   |
| Verification of elevator car lighting                                         | ✓                   |
| <b>Задаци на доњем прилазу за аутоматска врата</b>                            | <b>Modul status</b> |
| Verification of landing door bottom guides                                    | ✓                   |
| Verification of landing door closed gap                                       | ✓                   |
| <b>Задаци на спрату MAP-а</b>                                                 | <b>Modul status</b> |
| Verification of residual current device                                       | ✓                   |
| Verification of the emergency function and the related emergency power supply | ✓                   |
| <b>Задаци у кабини са затвореним вратима</b>                                  | <b>Modul status</b> |
| Verification of signs                                                         | ✓                   |
| Verification of elevator car interior                                         | ✓                   |
| Verification of car signalization; where installed                            | ✓                   |
| Verification of elevator car door panels                                      | ✓                   |
| Verification of car door bottom guides                                        | ✓                   |
| <b>Задаци на међуприлазима и на највишем прилазу</b>                          | <b>Modul status</b> |
| Verification of landing door sill                                             | ✓                   |
| Verification of entrance and corridor                                         | ✓                   |
| Verification of landing signalization                                         | ✓                   |
| Verification of landing door panels and landing door running                  | ✓                   |
| <b>Задаци на доњем прилазу</b>                                                | <b>Modul status</b> |
| Провера јаме лифта                                                            | ✓                   |
| <b>Завршите посету одржавања</b>                                              | <b>Modul status</b> |
| Verification of filled maintenance logbook                                    | ✓                   |
| Verification of returning the unit to normal operation                        | ✓                   |

Ovo je evidencija o završetku gore pomenutih modula održavanja. Ukoliko postoje stavke na koje moramo da vam skrenemo pažnju, nakon ove posete član našeg tima će vam se javiti.

**Komentari tehničara**

Redovan servis lifta

**Potpis Kupca**



**Ime kupca**

872388612  
Ivan

"Ovaj imejl se automatski kreira OBAVEŠTENJE: Informacije koje su sadržane u ovom imejlu i svi prilozi su strogo privatni i poverljivi i mogu imati zakonske privilegije. Ukoliko vi niste primalac koji je trebalo da dobije imejl, molimo kontaktirajte pošiljaoca povratnim imejlom. U ovom slučaju ne treba da koristite, razlašavate, distribuirate, reprodukujete, skladištite ili postupate u skladu sa ovim mejlom ili bilo kojim priložima, treba da uništite ovaj imejl i sve priloge ili kopije. Preduzeli smo mere predostrožnosti da umanjimo rizik od prenošenja softverskih virusa, ali vam savetujemo da sami izvršite proveru virusa na ovom imejlu i svim priložima koje sadrži. Ne možemo prihvatiti odgovornost za bilo koji gubitak ili štetu izazvanu softverskim virusima. Kone d.o.o., Omladinskih Brigada 90 D, sprat 6, 11070 Beograd-Novi Beograd, telefon: +381 11 3591 230, email: ksb.info@KONE.com"